

VIA AIRBORNE EXPRESS

650 Liberty Ave. Union, NJ 07083-8107 201 851-2200

109482

August 18, 1988

Mr. William D. Steuteville U.S. Environmental Protection Agency 841 Chestnut Building Philadelphia, PA 19107

RE: Monthly Inspection and Cable Casing Removal
C&D Recycling Site
Foster Township, PA

Dear Bill:

Enclosed is the monthly inspection and maintenance report for the C&D Recycling Site.

The core drilling rig has been removed from the site and the portion of the silt fence section 14 previously removed will be reinstalled. (This section may need to be temporarily removed again if the core hole near section 14 is developed into a monitoring well.)

The inspection report also indicates that some areas of fabric liner are visible in the drainage channel. Additional rip rap stone will be placed in these areas prior to or during the next monthly inspection.

We are in the process of contracting with remediation and transportation firms for the loading and transport of the cable casings. Kaiser International, the purchaser of the cable casings, is also in the process of finalizing details for the baling, shipment and processing of the cable casings.

One problem that has developed is that the Zozzaro Bros. facility in Clifton, New Jersey that had been selected for the baling of the casings is presently very busy baling cans, paper and cardboard resulting from municipal recycling programs and can not bale our casings at this time. We have found another baling facility in New Jersey that has excess capacity and we have requested the approval of NJDEP for the use of this facility. Assuming that we receive NJDEP approval, I will provide you with the approval letter and any other information that you need for your review.



Our tentative schedule is to start the removal during the week of September 12. I will keep you advised of further developments and let you know when the start date is finalized.

Please contact me if you have any comments or questions regarding the above.

Sincerely,

Larry A. Elder Senior Engineer

Encl.

C&D RECYCLING SITE

MONTHLY INSPECTION AND MAINTENANCE REPORT

SEC ⁻	TION I - GENERAL	SHICHNAL BURNAL
B.E.	S. Environmental Specialists, Inc.	· ··caj
1.	Name of Company Performing Inspection:	
	B.E.S. Environmental Specialists, Inc.	
2.	Name of Inspector:	
	Donald Scavone	
3.	Beginning Date of this Inspection:	
	08/05/88	
4.	Site Map Reviewed:	,
	YES 08/05/88	
5.	Previous Inspection and Maintenance Report Reviewed:	
	YES 08/05/88	
6.	Date of Previous Inspection:	
	Friday 07/05/88	
7.	Were any maintenance activities required on previous ins	pection report in
	which corrective action was not taken? <u>YES</u>	If so, which
	activities were not completed.	

Portion of silt fence section 14 removed for drilling.

DRIGINAL (Red)

SECTION II - FIELD INSPECTION

(A site map must be taken to site.)

- Site Security Fence: Walk Perimeter Note Location of Deficiencies on Site Map.
- o Warning Signs Intact? Yes X No If Not, Action Taken
- o Chain Link Fence Intact? Yes X No ___ If Not, Action Taken
- o Barbed Wire Intact? Yes X No ___ If Not, Action Taken
- o Gates Intact? Yes X No If Not, Action Taken
- o Tension Wire Intact? Yes X No ___ If Not, Action Taken
- o Chain & Padlocks Intact? Yes X No ___ If Not, Action Taken
- o Additional Observations (Erosion under fence, loss of post support, etc.).



Temporary Ash Cover: 1	Inspect	all	three	piles	individually.
--	---------	-----	-------	-------	---------------

Northern Pile

- o Plastic Cover Infact? Yes X No ___ If Not, Action Taken
- o Tire Hold-Down Intact? Yes x No ___ If Not, Action Taken
- o Perimeter Drainage Channel Intact? Yes X No ___ If Not, Action Taken
- o Additional Observations.

Central Pile

- o Plastic Cover Intact? Yes X No If Not, Action Taken
- o Tire Hold-Down Intact? Yes X No ___ If Not, Action Taken



0	Perimeter	Drainage	Channel	Intact?	Yes	X	No	Ιf	Not,	Action	Taken
			,								

Additional Observations.

Southern Pile

- o Plastic Cover Intact? Yes X No ___ If Not, Action Taken
- o Tire Hold-Down Intact? Yes X No ___ If Not, Action Taken
- o Perimeter Drainage Channel Intact? Yes X No ___ If Not, Action Taken
- o Additional Observations.
- Drainage Channel: Walk entire length Note location of deficiencies on Site Map.
- o Riprap Layer Intact? Yes ___ No _X If Not, Action Taken

 Filter fabric was showing as indicated on map.



0	Geotextile Intact? Yes X No If Not, Action Taken
o	Subgrade providing adequate support to bottom and sideslopes? Yes \underline{X} No If Not, Action Taken
0	Channel Unobstructed? Yes X No If Not, Action Taken
6	Additional Observations.
4.	Silt Fence: Walk all reaches - note location of deficiencies on Site Map.
0	Silt Fence Intact? Yes X No If Not, Action Taken
0	Fabric Secured to Posts? Yes \times No If Not, Action Taken
0	Fabric Entrenched Into Soil? Yes X No If Not, Action Taken

o Additional Observations.

Not, Action Taken

0

Silt fence #14 was run over by drillers. I informed them about it and they said they would repair the fence.

Runoff Flowing Through Fence and Not Around Fence. Yes \times No ____ If



- 5. CMP Drainage Pipe Downdrain: Walk entire length note location of deficiencies on Site Map.
- o Pipe Connections Intact? Yes $\underline{\times}$ No $\underline{\hspace{0.5cm}}$ If Not, Action Taken
- o Anchor Bars Embedded and Intact? Yes $\underline{\times}$ No $\underline{\hspace{0.5cm}}$ If Not, Action Taken
- o Outlet Area Intact? Yes X No ___ If Not, Action Taken
- o Pipe Outlet Unobstructed? Yes \underline{X} No $\underline{\hspace{1cm}}$ If Not, Action Taken
- o Additional Observations.



SECTION III - SUMMARY

Date Inspection and Maintenance Activities were completed: 08/05/88

List of maintenance activities which were not completed at the time that this report was prepared:

- Portion of silt fence section 14 to be reinstalled.
- Additional rip rap stone to be placed on exposed areas of fabric in drainage channel.

Amal Scroon 8.5-88

SIGNATURE OF INSPECTOR/DATE